

Gently tap hydrometer to release any air bubles.

Read the density where the water line meets the hydrometer stem.

Hold at eye level for precise measurements.

Record density to 4 decimal places: 1.0 ___ __ __